



# CERTIFICATE OF EXAMINATION

ASH 304

Complete

Score	55 / 55 (100%)	Flagged items	0	Actions	0
-------	----------------	---------------	---	---------	---

Site conducted

DU0001 Old Rectory Drive,  
Hatfield

Conducted on

29 Nov 2023 8:32 AM GMT

Prepared by

A bunker

Location

29 Howe Dell, Hatfield AL10  
8BW, UK  
(51.760875399999996,  
-0.2195459)

Asset

ASH 304  
3 Ton dumper - Dumper 3t Terex

Asset serial number

10ar266

Asset hours

0

Supply photo's of asset



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6

Power unit	11 / 11 (100%)
Oil level	Acceptable
Water/Antifreeze level	N/A
Belt tension/Condition	Acceptable
Mountings	Acceptable
Emissions/Exhaust	Acceptable
Oil leaks	Acceptable
Hoses & pipes	Acceptable
Gauges/Warning indicators	N/A
Turbo	N/A
Air cleaner/Indicator	Acceptable
Spark Arrestor	N/A

<b>Transmission</b>		5 / 5 (100%)
Oil levels/Leaks		<b>Acceptable</b>
Controls/Operations		<b>Acceptable</b>
Drive shafts/Axles		<b>Acceptable</b>
Hub reduction units/levels		<b>Acceptable</b>
Transfer box/levels		<b>Acceptable</b>

<b>Brakes</b>		5 / 5 (100%)
Air/Hydraulic leaks		<b>Acceptable</b>
Drums/Discs/Pads/Shoes		<b>Acceptable</b>
Foot/Hand controls		<b>Acceptable</b>
Cables/Rods/Pipes		<b>Acceptable</b>
Fluid levels/Efficiency		<b>Acceptable</b>

<b>Steering</b>	6 / 6 (100%)
Box/Column/Wheel	<b>Acceptable</b>
King Pins/Bushes	<b>Acceptable</b>
Ramp/Pump/Hoses	<b>Acceptable</b>
Track Rods/Steering Arms	<b>Acceptable</b>
Linkages/Ball joints	<b>Acceptable</b>
Oil levels/Leakes	<b>Acceptable</b>

<b>Running Gear</b>	5 / 5 (100%)
Tyres/Wheels/Tracks	<b>Acceptable</b>
Wheel bearings	<b>Acceptable</b>
Axle security	<b>Acceptable</b>
Over run brake rods/cable	<b>Acceptable</b>
Towing/Frame Attachments	<b>Acceptable</b>

<b>Fuel System</b>		4 / 4 (100%)
Fuel tank/Security		<b>Acceptable</b>
Fuel line/leaks		<b>Acceptable</b>
Filters/Pumps		<b>Acceptable</b>
Fuel level/Gauge		<b>Acceptable</b>

<b>Hydraulics</b>		5 / 5 (100%)
Rams		<b>Acceptable</b>
Pumps/Hoses/Pipes		<b>Acceptable</b>
Safety indicators		<b>N/A</b>
Oil levels/leaks		<b>Acceptable</b>
Controls		<b>Acceptable</b>



<b>Electrical</b>	10 / 10 (100%)
Battery	Acceptable
Alternator/Charging	Acceptable
Wiring	Acceptable
Fuses/Circuit breakers	Acceptable
Lights/Indicators	N/A
Warning Indicators	N/A
Outlet sockets	N/A
Limit/Proximity switches	Acceptable
Safety Devices	Acceptable
Warning Devices	Acceptable

<b>Cab</b>	4 / 4 (100%)
Seating/Belts	Acceptable
Structure/Rops	Acceptable
Glass/Mirrors	N/A
Mountings	Acceptable

## Sign off

Engineers name & signature

**a bunker**  
**29 Nov 2023 8:37 AM GMT**

---

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6