Record No: 2023/07/406/117772

RECORD OF THOROUGH EXAMINATION OF LIFTING PLANT AND EQUIPMENT

IN ACCORDANCE WITH THE LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998 (LOLER)

	Diesel Hydraulic Excavator
Description of equipment	Kubota KX027-4
Identification mark of equipment	Pno ASH 40 Sno KBCGJ11BHNZE58162
Name and address of owner of equipment	Ashvale Plant Hire Ltd
	Firbank Trading Estate
	Luton
	LU1 1TD
Date of the most recent test and examination and	N/A
identification of the record issued on that occasion	
Date of the last examination and identification of	August 2022
the records issued on that occasion	
Safe working load or loads and (where relevant)	Refer to Manufacturers Lifting Charts & Radii Tables
corresponding radii	
Details of any defects found (if none state NONE)	None
Date(s) by which defects described above must be rectified	
What parts if any were inaccessible? (TO BE COMPLETED ONLY AFTER A THOROUGH EXAMINATION OF A HOIST OR LIFT)	Enclosed parts of hydraulic system
Latest date by which the next thorough	27 th JULY 2024
examination must be carried out	
Examined at	Yard
Other notes	Always ensure that the correct operator's instructions are in the
	machine and that the correct SWL is clearly marked on the Boom or
	elsewhere on the machine. For Full SWL specifications always Refer to Manufacturers Lifting/Radii Tables.

Declaration

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and found free from any defect likely to affect safety other than those listed above on **27/07/2023** and that the above particulars are correct.

Signature or other identification

Allen Lee. Engineering Surveyor

Mentee

Name and address of person authenticating the record and responsible for the thorough examination.

Sky Technical Services Ltd

4 Victoria Cottages

Love Lane, Mayfield, E.Sussex. TN20 6EN . Tel 01435 873355 / 07703 292932. Email info@skytechnical.co.uk

Date the record is made 28/07/2023