

ASHVALE PLANT HIRE LTD - CERTIFICATE OF EXAMINATION

CUSTOMER NAME & ADDRESS	DATE IN	25/04/23
	DATE OUT	
	MACHINE DETAILS	
	MAKE	Benford
SITE ADDRESS	MODEL	SR10
Ostensa Drive	SERIAL NO	SYVH1270
	PLANT NO	903
	HOURS	

CODES: ✓ = SERVICEABLE X = UNSERVICEABLE

1	POWER UNIT	4	STEERING	8	ELECTRICAL
A	OIL LEVEL	✓ A	BOX/COLUMN/WHEEL	✓ A	BATTERY
B	WATER/ANTIFREEZE LEVEL	✓ B	KING PINS/BUSHES	✓ B	ALTERNATOR/CHARGING
C	BELT TENSION/CONDITION	✓ C	RAMP/PUMP/HOSES	C	WIRING
D	MOUNTINGS	✓ D	TRACK RODS/STEERING ARMS	✓ D	FUSES/CIRCUIT BREAKERS
E	EMISSIONS/EXHAUST	✓ E	LINKAGES/BALL JOINTS	E	LIGHTS/INDICATORS
F	OIL LEAKS	✓ F	OIL LEVELS/LEAKS	✓ F	WARNING INDICATORS
G	HOSES AND PIPES			G	OUTLET SOCKETS
H	GAUGES/WARNING INDICATORS	5	RUNNING GEAR	H	LIMIT/PROXIMITY SWITCHES
I	TURBO	✓ A	TYRES/WHEELS/TRACKS	✓ I	SAFETY DEVICES
J	AIR CLEANER/INDICATOR	✓ B	WHEEL BEARINGS	✓ J	WARNING DEVICES
K	SPARK ARRESTOR	C	AXLE SECURITY	✓	
		D	OVER RUN BRAKE RODS/CABLE	9	CAB
2	TRANSMISSION	E	TOWING/FRAME ATTACHMENTS	A	SEATING/BELTS
A	OIL LEVELS/LEAKS	✓		B	STRUCTURE/ROPS
B	CONTROLS/OPERATIONS	✓ 6	FUEL SYSTEM	C	GLASS/MIRRORS
C	DRIVE SHAFTS/AXLES	✓ A	FUEL TANK/SECURITY	✓ D	MOUNTINGS
D	HUB REDUCTION UNITS/LEVELS	✓ B	FUEL LINES/LEAKS	✓	
E	TRANSFER BOX/LEVELS	✓ C	FILTERS/PUMPS	✓ 10	GENERAL
		D	FUELLEVEL/GAUGE	✓ A	MACHINE MAIN STRUCTURE
3	BRAKES			B	BUCKET/FOR/SKIP
A	AIR/HYDRAULIC LEAKS	✓ 7	HYDRAULICS	C	ROPES/DRUMS/HOOK BLOCKS
B	DRUMS/DISCS/PADS/SHOES	✓ A	RAMS	✓ D	MAST/JIB/BOOM
C	FOOT/HAND CONTROLS	✓ B	PUMPS/HOSES/PIPES	✓ E	SCISSOR PACK
D	CABLES/RODS/PIPES	✓ C	SAFETY INDICATORS	F	LOAD INDICATOR
E	FLUID LEVELS/EFFICIENCY	✓ D	OIL LEVELS/LEAKS	✓ G	DECALS
		E	CONTROLS	✓ H	THOROUGH EXAM REPORT
				I	OPERATORS MANUAL
				J	GREASE NIPPLES
				K	FULLY GREASED

DEFECT	ACTION TAKEN

THIS MACHINE WAS INSPECTED ON 25/04/23 AND SUBJECT TO ANY REPAIRS NOTED ABOVE BEING CARRIED OUT IS IN A SAFE CONDITION TO USE.

ENGINEERS SIGNATURE *[Signature]*