

ASHVALE PLANT HIRE LTD - CERTIFICATE OF EXAMINATION

CUSTOMER NAME & ADDRESS <i>D. Leighton</i>	DATE IN <i>24-4-23</i>	
	DATE OUT <i>24-4-23</i>	
	MACHINE DETAILS	
	MAKE <i>Thomson</i>	
SITE ADDRESS <i>S. Anneton Rd Chobham Berkhamstead</i>	MODEL <i>9 ton</i>	
	SERIAL NO	
	PLANT NO <i>ASH 910</i>	
	HOURS	

CODES: ✓ = SERVICEABLE X = UNSERVICEABLE

1 POWER UNIT	4 STEERING	8 ELECTRICAL
A OIL LEVEL ✓	A BOX/COLUMN/WHEEL ✓	A BATTERY ✓
B WATER/ANTIFREEZE LEVEL ✓	B KING PINS/BUSHES ✓	B ALTERNATOR/CHARGING ✓
C BELT TENSION/CONDITION ✓	C RAMP/PUMP/HOSES ✓	C WIRING ✓
D MOUNTINGS ✓	D TRACK RODS/STEERING ARMS ✓	D FUSES/CIRCUIT BREAKERS ✓
E EMISSIONS/EXHAUST ✓	E LINKAGES/BALL JOINTS ✓	E LIGHTS/INDICATORS ✓
F OIL LEAKS ✓	F OIL LEVELS/LEAKS ✓	F WARNING INDICATORS ✓
G HOSES AND PIPES ✓		G OUTLET SOCKETS ✓
H GAUGES/WARNING INDICATORS ✓	5 RUNNING GEAR	H LIMIT/PROXIMITY SWITCHES ✓
I TURBO ✓	A TYRES/WHEELS/TRACKS ✓	I SAFETY DEVICES ✓
J AIR CLEANER/INDICATOR ✓	B WHEEL BEARINGS ✓	J WARNING DEVICES ✓
K SPARK ARRESTOR ✓	C AXLE SECURITY ✓	
	D OVER RUN BRAKE RODS/CABLE ✓	9 CAB
2 TRANSMISSION	E TOWING/FRAME ATTACHMENTS ✓	A SEATING/BELTS ✓
A OIL LEVELS/LEAKS ✓		B STRUCTURE/ROPS ✓
B CONTROLS/OPERATIONS ✓	6 FUEL SYSTEM	C GLASS/MIRRORS ✓
C DRIVE SHAFTS/AXLES ✓	A FUEL TANK/SECURITY ✓	D MOUNTINGS ✓
D HUB REDUCTION UNITS/LEVELS ✓	B FUEL LINES/LEAKS ✓	
E TRANSFER BOX/LEVELS ✓	C FILTERS/PUMPS ✓	10 GENERAL
	D FUELLEVEL/GAUGE ✓	A MACHINE MAIN STRUCTURE ✓
3 BRAKES		B BUCKET/FOR/SKIP ✓
A AIR/HYDRAULIC LEAKS ✓	7 HYDRAULICS	C ROPES/DRUMS/HOOK BLOCKS ✓
B DRUMS/DISCS/PADS/SHOES ✓	A RAMS ✓	D MAST/JIB/BOOM ✓
C FOOT/HAND CONTROLS ✓	B PUMPS/HOSES/PIPES ✓	E SCISSOR PACK ✓
D CABLES/RODS/PIPES ✓	C SAFETY INDICATORS ✓	F LOAD INDICATOR ✓
E FLUID LEVELS/EFFICIENCY ✓	D OIL LEVELS/LEAKS ✓	G DECALS ✓
	E CONTROLS ✓	H THOROUGH EXAM REPORT ✓
		I OPERATORS MANUAL ✓
		J GREASE NIPPLES ✓
		K FULLY GREASED ✓

DEFECT	ACTION TAKEN
<i>R1 wheel</i>	<i>Tyre cracked</i>
<i>Hand Brake</i>	<i>Adjusted hand brake</i>
<i>Director selector</i>	<i>Belt missing secured temp</i>

THIS MACHINE WAS INSPECTED ON 24/4/23 AND SUBJECT TO ANY REPAIRS NOTED ABOVE BEING CARRIED OUT IS IN A SAFE CONDITION TO USE.

ENGINEERS SIGNATURE *[Signature]*