



# CERTIFICATE OF EXAMINATION

ASH 917

Complete

Score	55 / 55 (100%)	Flagged items	0	Actions	0
-------	----------------	---------------	---	---------	---

Site conducted

AB0020 Cromwell Place,  
Wixams, ABBEY NEW HOMES

Conducted on

27 Nov 2023 8:37 AM GMT

Prepared by

A bunker

Location

A6, Bedford MK42 9YG, UK  
(52.106173,  
-0.47383179999999997)

Asset

ASH 917  
9 Ton Dumper - Dumper 9T  
Thwaites MACH 2290

Asset serial number

7f5765

Asset hours

631

Supply photo's of asset




Photo 1




Photo 2




Photo 3




Photo 4

Power unit	11 / 11 (100%)
Oil level	Acceptable
Water/Antifreeze level	Acceptable
Belt tension/Condition	Acceptable
Mountings	Acceptable
Emissions/Exhaust	Acceptable
Oil leaks	Acceptable
Hoses & pipes	Acceptable
Gauges/Warning indicators	Acceptable
Turbo	Acceptable
Air cleaner/Indicator	Acceptable
Spark Arrestor	Acceptable

<b>Transmission</b>		5 / 5 (100%)
Oil levels/Leaks		<b>Acceptable</b>
Controls/Operations		<b>Acceptable</b>
Drive shafts/Axles		<b>Acceptable</b>
Hub reduction units/levels		<b>Acceptable</b>
Transfer box/levels		<b>Acceptable</b>

<b>Brakes</b>		5 / 5 (100%)
Air/Hydraulic leaks		<b>Acceptable</b>
Drums/Discs/Pads/Shoes		<b>Acceptable</b>
Foot/Hand controls		<b>Acceptable</b>
Cables/Rods/Pipes		<b>Acceptable</b>
Fluid levels/Efficiency		<b>Acceptable</b>

<b>Steering</b>	6 / 6 (100%)
Box/Column/Wheel	<b>Acceptable</b>
King Pins/Bushes	<b>Acceptable</b>
Ramp/Pump/Hoses	<b>Acceptable</b>
Track Rods/Steering Arms	<b>Acceptable</b>
Linkages/Ball joints	<b>Acceptable</b>
Oil levels/Leakes	<b>Acceptable</b>

<b>Running Gear</b>		5 / 5 (100%)
Tyres/Wheels/Tracks		<b>Acceptable</b>
Wheel bearings		<b>Acceptable</b>
Axle security		<b>Acceptable</b>
Over run brake rods/cable		<b>N/A</b>
Towing/Frame Attachments		<b>Acceptable</b>

<b>Fuel System</b>		4 / 4 (100%)
Fuel tank/Security		<b>Acceptable</b>
Fuel line/leaks		<b>Acceptable</b>
Filters/Pumps		<b>Acceptable</b>
Fuel level/Gauge		<b>Acceptable</b>

<b>Hydraulics</b>		5 / 5 (100%)
Rams		<b>Acceptable</b>
Pumps/Hoses/Pipes		<b>Acceptable</b>
Safety indicators		<b>N/A</b>
Oil levels/leaks		<b>Acceptable</b>
Controls		<b>Acceptable</b>



<b>Electrical</b>	10 / 10 (100%)
Battery	Acceptable
Alternator/Charging	Acceptable
Wiring	Acceptable
Fuses/Circuit breakers	Acceptable
Lights/Indicators	N/A
Warning Indicators	Acceptable
Outlet sockets	N/A
Limit/Proximity switches	Acceptable
Safety Devices	Acceptable
Warning Devices	Acceptable

<b>Cab</b>	4 / 4 (100%)
Seating/Belts	Acceptable
Structure/Rops	Acceptable
Glass/Mirrors	N/A
Mountings	N/A

## Sign off

Engineers name & signature

A handwritten signature in black ink, appearing to be 'a bunker', written in a cursive style.

**a bunker**  
**27 Nov 2023 8:44 AM GMT**

---

## Media summary




Photo 1




Photo 2




Photo 3




Photo 4