



CERTIFICATE OF EXAMINATION

ASH 919

Complete

Score	55 / 55 (100%)	Flagged items	0	Actions	0
-------	----------------	---------------	---	---------	---

Site conducted **GH001 Hayle Field, Thurleigh**

Conducted on **28 Nov 2023 3:16 PM GMT**

Prepared by **A bunker**

Location **66 High St, Thurleigh, Bedford
MK44 2DX, UK
(52.214206,
-0.45345840000000004)**

Asset **ASH 919
9 Ton Dumper - Dumper 9T
Thwaites MACH 2290**

Asset serial number **7f5953**

Asset hours **516**

Supply photo's of asset



Photo 1



Photo 2



Photo 3



Photo 4

Power unit	11 / 11 (100%)
Oil level	Acceptable
Water/Antifreeze level	Acceptable
Belt tension/Condition	Acceptable
Mountings	Acceptable
Emissions/Exhaust	Acceptable
Oil leaks	Acceptable
Hoses & pipes	Acceptable
Gauges/Warning indicators	Acceptable
Turbo	Acceptable
Air cleaner/Indicator	Acceptable
Spark Arrestor	N/A

Transmission		5 / 5 (100%)
Oil levels/Leaks		Acceptable
Controls/Operations		Acceptable
Drive shafts/Axles		Acceptable
Hub reduction units/levels		Acceptable
Transfer box/levels		Acceptable

Brakes	5 / 5 (100%)
Air/Hydraulic leaks	Acceptable
Drums/Discs/Pads/Shoes	Acceptable
Foot/Hand controls	Acceptable
Cables/Rods/Pipes	Acceptable
Fluid levels/Efficiency	Acceptable

Steering	6 / 6 (100%)
Box/Column/Wheel	Acceptable
King Pins/Bushes	Acceptable
Ramp/Pump/Hoses	Acceptable
Track Rods/Steering Arms	Acceptable
Linkages/Ball joints	Acceptable
Oil levels/Leakes	Acceptable

Running Gear		5 / 5 (100%)
Tyres/Wheels/Tracks		Acceptable
Wheel bearings		Acceptable
Axle security		Acceptable
Over run brake rods/cable		N/A
Towing/Frame Attachments		Acceptable

Fuel System		4 / 4 (100%)
Fuel tank/Security		Acceptable
Fuel line/leaks		Acceptable
Filters/Pumps		Acceptable
Fuel level/Gauge		Acceptable

Hydraulics		5 / 5 (100%)
Rams		Acceptable
Pumps/Hoses/Pipes		Acceptable
Safety indicators		Acceptable
Oil levels/leaks		Acceptable
Controls		Acceptable

Electrical	10 / 10 (100%)
Battery	Acceptable
Alternator/Charging	Acceptable
Wiring	Acceptable
Fuses/Circuit breakers	Acceptable
Lights/Indicators	N/A
Warning Indicators	Acceptable
Outlet sockets	N/A
Limit/Proximity switches	Acceptable
Safety Devices	Acceptable
Warning Devices	Acceptable

Cab	4 / 4 (100%)
Seating/Belts	Acceptable
Structure/Rops	Acceptable
Glass/Mirrors	N/A
Mountings	N/A

Sign off

Engineers name & signature

a bunker
28 Nov 2023 3:19 PM GMT

Media summary

LAT:52.214525 LON:-0.451217



Photo 1

LAT:52.214525 LON:-0.451217



Photo 2

LAT:52.214525 LON:-0.451217



Photo 3

LAT:52.214525 LON:-0.451217



Photo 4