

ASHVALE PLANT HIRE LTD - CERTIFICATE OF EXAMINATION

CUSTOMER NAME & ADDRESS	DATE IN	20/4/23
ASHVALE	DATE OUT	
	MACHINE DETAILS	
	MAKE	MECALOR
SITE ADDRESS	MODEL	MBR71
Cheriton	SERIAL NO	SLBPO03Z0EJ2PM1865
	PLANT NO	PE002
	HOURS	

CODES: ✓ = SERVICEABLE X = UNSERVICEABLE

1 POWER UNIT	4 STEERING	8 ELECTRICAL
A OIL LEVEL ✓	A BOX/COLUMN/WHEEL	A BATTERY ✓
B WATER/ANTIFREEZE LEVEL ✓	B KING PINS/BUSHES ✓	B ALTERNATOR/CHARGING ✓
C BELT TENSION/CONDITION ✓	C RAMP/PUMP/HOSES	C WIRING ✓
D MOUNTINGS ✓	D TRACK RODS/STEERING ARMS	D FUSES/CIRCUIT BREAKERS ✓
E EMISSIONS/EXHAUST ✓	E LINKAGES/BALL JOINTS	E LIGHTS/INDICATORS
F OIL LEAKS ✓	F OIL LEVELS/LEAKS	F WARNING INDICATORS ✓
G HOSES AND PIPES ✓		G OUTLET SOCKETS
H GAUGES/WARNING INDICATORS ✓	5 RUNNING GEAR	H LIMIT/PROXIMITY SWITCHES
I TURBO	A TYRES/WHEELS/TRACKS	I SAFETY DEVICES ✓
J AIR CLEANER/INDICATOR ✓	B WHEEL BEARINGS	J WARNING DEVICES ✓
K SPARK ARRESTOR	C AXLE SECURITY	
	D OVER RUN BRAKE RODS/CABLE	9 CAB
2 TRANSMISSION	E TOWING/FRAME ATTACHMENTS	A SEATING/BELTS
A OIL LEVELS/LEAKS		B STRUCTURE/ROPS
B CONTROLS/OPERATIONS ✓	6 FUEL SYSTEM	C GLASS/MIRRORS
C DRIVE SHAFTS/AXLES	A FUEL TANK/SECURITY	D MOUNTINGS
D HUB REDUCTION UNITS/LEVELS	B FUEL LINES/LEAKS ✓	
E TRANSFER BOX/LEVELS	C FILTERS/PUMPS ✓	10 GENERAL
	D FUELLEVEL/GAUGE ✓	A MACHINE MAIN STRUCTURE ✓
3 BRAKES		B BUCKET/FOR/SKIP
A AIR/HYDRAULIC LEAKS ✓	7 HYDRAULICS	C ROPES/DRUMS/HOOK BLOCKS ✓
B DRUMS/DISCS/PADS/SHOES ✓	A RAMS ✓	D MAST/JIB/BOOM
C FOOT/HAND CONTROLS ✓	B PUMPS/HOSES/PIPES ✓	E SCISSOR PACK
D CABLES/RODS/PIPES	C SAFETY INDICATORS	F LOAD INDICATOR
E FLUID LEVELS/EFFICIENCY ✓	D OIL LEVELS/LEAKS ✓	G DECALS ✓
	E CONTROLS ✓	H THOROUGH EXAM REPORT ✓
		I OPERATORS MANUAL
		J GREASE NIPPLES ✓
		K FULLY GREASED ✓

DEFECT	ACTION TAKEN

THIS MACHINE WAS INSPECTED ON 20/4/23 AND SUBJECT TO ANY REPAIRS NOTED ABOVE BEING CARRIED OUT IS IN A SAFE CONDITION TO USE.

ENGINEERS SIGNATURE