



# CERTIFICATE OF EXAMINATION

ROR 11

Complete

|       |                |               |   |         |   |
|-------|----------------|---------------|---|---------|---|
| Score | 55 / 55 (100%) | Flagged items | 0 | Actions | 0 |
|-------|----------------|---------------|---|---------|---|

Site conducted **AB0015 Ortensia Drive, Wavendon, ABBEY NEW HOMES**

Conducted on **1 Dec 2023 2:38 PM GMT**

Prepared by **A bunker**

Location **13 Pierres Pl, Glebe Farm, Wavendon, Milton Keynes MK17 8GF, UK (52.027054199999995, -0.6782841)**

Asset **ROR 11 Roller - Hamm 120 Roller - 12VV**

Asset serial number **3747**

Asset hours **1140**

Supply photo's of asset



Photo 1



Photo 2



Photo 3



Photo 4




Photo 5



Photo 6



Photo 7



Photo 8




Photo 9

| Power unit                | 11 / 11 (100%) |
|---------------------------|----------------|
| Oil level                 | Acceptable     |
| Water/Antifreeze level    | Acceptable     |
| Belt tension/Condition    | Acceptable     |
| Mountings                 | Acceptable     |
| Emissions/Exhaust         | Acceptable     |
| Oil leaks                 | Acceptable     |
| Hoses & pipes             | Acceptable     |
| Gauges/Warning indicators | N/A            |
| Turbo                     | N/A            |
| Air cleaner/Indicator     | Acceptable     |
| Spark Arrestor            | N/A            |

| <b>Transmission</b>        |  | 5 / 5 (100%)      |
|----------------------------|--|-------------------|
| Oil levels/Leaks           |  | <b>Acceptable</b> |
| Controls/Operations        |  | <b>Acceptable</b> |
| Drive shafts/Axles         |  | <b>Acceptable</b> |
| Hub reduction units/levels |  | <b>Acceptable</b> |
| Transfer box/levels        |  | <b>Acceptable</b> |

| <b>Brakes</b>           |  | 5 / 5 (100%)      |
|-------------------------|--|-------------------|
| Air/Hydraulic leaks     |  | <b>Acceptable</b> |
| Drums/Discs/Pads/Shoes  |  | <b>Acceptable</b> |
| Foot/Hand controls      |  | <b>Acceptable</b> |
| Cables/Rods/Pipes       |  | <b>Acceptable</b> |
| Fluid levels/Efficiency |  | <b>Acceptable</b> |

| <b>Steering</b>          | 6 / 6 (100%) |
|--------------------------|--------------|
| Box/Column/Wheel         | Acceptable   |
| King Pins/Bushes         | Acceptable   |
| Ramp/Pump/Hoses          | Acceptable   |
| Track Rods/Steering Arms | Acceptable   |
| Linkages/Ball joints     | Acceptable   |
| Oil levels/Leakes        | Acceptable   |

| Running Gear              | 5 / 5 (100%) |
|---------------------------|--------------|
| Tyres/Wheels/Tracks       | Acceptable   |
| Wheel bearings            | Acceptable   |
| Axle security             | Acceptable   |
| Over run brake rods/cable | N/A          |
| Towing/Frame Attachments  | N/A          |

| <b>Fuel System</b> | 4 / 4 (100%) |
|--------------------|--------------|
| Fuel tank/Security | Acceptable   |
| Fuel line/leaks    | Acceptable   |
| Filters/Pumps      | Acceptable   |
| Fuel level/Gauge   | Acceptable   |

| <b>Hydraulics</b> |  | 5 / 5 (100%)      |
|-------------------|--|-------------------|
| Rams              |  | <b>Acceptable</b> |
| Pumps/Hoses/Pipes |  | <b>Acceptable</b> |
| Safety indicators |  | <b>Acceptable</b> |
| Oil levels/leaks  |  | <b>Acceptable</b> |
| Controls          |  | <b>Acceptable</b> |



| <b>Electrical</b>        | 10 / 10 (100%) |
|--------------------------|----------------|
| Battery                  | Acceptable     |
| Alternator/Charging      | Acceptable     |
| Wiring                   | Acceptable     |
| Fuses/Circuit breakers   | Acceptable     |
| Lights/Indicators        | Acceptable     |
| Warning Indicators       | Acceptable     |
| Outlet sockets           | N/A            |
| Limit/Proximity switches | Acceptable     |
| Safety Devices           | Acceptable     |
| Warning Devices          | Acceptable     |

| <b>Cab</b>     | 4 / 4 (100%) |
|----------------|--------------|
| Seating/Belts  | Acceptable   |
| Structure/Rops | Acceptable   |
| Glass/Mirrors  | N/A          |
| Mountings      | N/A          |

## Sign off

Engineers name & signature

**a bunker**  
**1 Dec 2023 2:41 PM GMT**

---

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9