






CERTIFICATE OF THOROUGH EXAMINATION

PREPARED IN ACCORDANCE WITH THE REQUIREMENTS OF LIFTING OPERATIONS
AND LIFTING EQUIPMENT REGULATIONS 1998 (LOLER)

Job No :- 200324

| | | |
|---|--|--|
| Owner: Ashvale Plant Hire Limited | Site Address : Pioneer Plant Ltd, Corby Workshop, NN17 4JW | |
| Manufacturer: Doosan / Geith | Model: DX225LC-7/ Geith Coupler | Serial No: DXCCEBDPCN0020188 / 1120371 |
| Machine Type: Excavator / Quick Hitch | Date of Manufacture: 2024 | Safe Working Load: excavator as per loadchart / hitch 17000kg |
| Reason for Thorough Examination (see Note): Twelve Monthly Under Reg 9 | | Test Carried out: Visual Inspection |
| Defective Parts/Areas: | | |
| Advised Repairs: | | To be Completed By: |
| Repairs/Renewal/Alteration Carried Out: | | |
| Defects Not Addressed: | | |
| Date of Last Examination: N/A | Date of Next Thorough Examination: 28/01/2024 | |
| Testing Carried Out: Visual Inspection Safe Working Load Data: excavator as per lodchart hitch 17000kg Lift Operation: Pass Frame/Load Guard: Pass Chain Cert No.: N/A Fork/Attachment: Pass Seat/Seat Belt: Pass Beacon Alarms: Pass Unit Safe to Operate: Yes | Inspection Carried out By: Print: James Chambers Service Engineer Sign:  Date: 29/01/2024 Verified By: Print: Steven Corner Service Manager Sign:  Date: 29/01/2024 | |
| NOTE: a: Six monthly under Reg. 9 (a) (i) b: Twelve monthly under Reg. 9 (3) (a) (ii) c: Examination scheme under Reg. 9 (3) (a) (iii) d: Exceptional Circumstances under Reg. 9 (3) (a) (iv) | CERTIFICATE NUMBER 455 / PP 2024 | |



CONSTRUCTION
SPECIALISTS

13 Brunel Road, Earlstrees Ind Est, Corby,
Northants, NN174JW
Telephone : 01536 697 571
E-mail : Info@pioneerplant.co.uk
Website : www.pioneerplant.co.uk
Company Reg No, 12487981