

CERTIFICATE OF THOROUGH EXAMINATION

PREPARED IN ACCORDANCE WITH THE REQUIREMENTS OF LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998 (LOLER)

Job No :- 200323

Owner: Ashvale Plant Hire Limited	Site Address : Pioneer Plant Ltd, Corby Workshop, NN17 4JW		
Manufacturer: Doosan / Geith	Model: DX225LC-7/ Geith Coupler		Serial No:DXCCEBDPEN0020182 / 1072591
Machine Type: Excavator / Quick Hitch	Date of Manufacture: 2024		Safe Working Load: excavator as per loadchart / hitch 17000kg
Reason for Thorough Examination (see Note): Twelve Monthly Under Reg 9		Test Carried out: Visual Inspection	
Defective Parts/Areas:			
Advised Repairs:		To be Completed By:	
Repairs/Renewal/Alteration Carried Out:			
Defects Not Addressed:			
Date of Last Examination: N/A		Date of Next Thorough Examination: 28/01/2024	
Testing Carried Out: Safe Working Load Data: Excavator as hitch 17000k Lift Operation: Frame/Load Guard: Chain Cert No.: Fork/Attachment: Seat/Seat Belt: Beacon Alarms: Unit Safe to Operate: Visual Inspect excavator as hitch 17000k Pass N/A Pass Pass Pass V/A	per lodchart	Inspection Carried Print: James Chamb Sign: Verified By: Print: Steven Corn Sign:	bers Service Engineer Date:29/01/2024
NOTE: a: Six monthly under Reg. 9 (a) (i) b: Twelve monthly under Reg. 9 (3) (a) (ii) c: Examination scheme under Reg. 9 (3) (a) (iii) d: Exceptional Circumstances under Reg. 9 (3) (a) (iv)		CERTIFICATE NUMBER 454 / PP 2024	



CONSTRUCTION SPECIALISTS

13 Brunel Road, Earlstrees Ind Est, Corby, Northants, NN174JW

Telephone: 01536 697 571
E-mail: Info@pioneerplant.co.uk
Website: www.pioneerplant.co.uk
Company Reg No, 12487981